

Daily Update April 25

Geological Work

Devil's Slide (post mile 39.14)

• Drilling operations to install inclinometers continued today. The second of four holes is complete. Drilling depth is 300 feet.



Drill rig in position at Devil's Slide

Slide at Post Mile 39.77

• Work on designing the repair for this relatively small slide is underway.

Repair Work

Slide at Post Mile 40

 Installation of drains was completed today. Additional rocks were placed at the base of the repair acting as a solid foundation for rebuilding the hillside.



Repair work continues to rebuild the hillside

Highway 92 Maintenance

 Overnight ditch clearing is complete along Highway 92. Work concentrated on stretches of road that motorist had identified as being potential problems. Maintenance issues along 92 will continue to be addressed during times that do not impede traffic.